


## VTM119+Surface Mounted Box



## Installation



**Step1** Drill holes in the wall according to holes on the surface mount box, and then put expansion tube in the holes.

**Step2** Fix the surface mount box on the wall with ST4×25 screws.

**Step3** Install M3×6 screws on the top of the surface mount box to prevent water leakage.

**Step4** Thread the cable through the bracket, and then connect the cables to cables on the wall.

**Step5** Fix the bracket on the surface mount box with M3×6 screws.


**Step6** Fix the outdoor station (VTO) on the bracket with M3×16 screws.

Step7 Apply sealant to gaps between the surface mount box and the wall.

© 2019 Dahua. All rights reserved. Design and specifications are subject to change without notice Pictures in the document are for reference only, and the actual product shall prevail.

## Dimensions (mm[inch])

Material: AL5052



•

• Dimensions: 150.2mm×411.3mm×127.0mm (5.91"×6.19"×5.00")



Rev 001.001

## +61 45 22 45 222